



# Tempest (Atari)

*Rendered on June 24, 2025*

---

Seems to be in just poor health  
Very obvious shipping damage inside, power supply was not bolted down. Thing went all over the place.  
Spent some time putting everything back, had to fix a pair of connectors.  
Raster engine was very buggy on startup but after a few minutes of running it seemed to come back to life.  
Not ideal, something in the PSU is not in good health. But as of right now it is working.  
PSU should be investigated for future problems.

---

**Date:** 2025-05-26, **Status:** Buggy

The LV Kit did arrive, didn't install it yet though.  
Tempest is ready for thursday's event



---

**Date:** 2025-06-10, **Status:** Working



## Service Log

Installed the LV board, everything went smooth. Screen looks improved but I still saw at least one inversion from left to right. I can only imagine the sweep happens somewhere else, will need to investigate. It didn't happen again when I was watching it but, it's still there even if it's better.





Service Log