



Tron (Cocktail)

Rendered on June 10, 2025

<p>Tron definitely has some issues playing smoothly Keeps going into a thermal-situation and loosing vsync? Very much resembles a poor connector Since its on the sync side its prolly the thicker black cable on the p5 header (big brown 7p or 9p wire) that runs to the display. Will leave it running but that whole collection of connectors should be cleaned.</p> <hr/> <p>Date: 2025-06-10, Status: Buggy</p>

<p>Yeah nevermind, the sync wont come back. Will disable it for thursday</p> <hr/> <p>Date: 2025-06-10, Status: Not-Playable</p>
--