



Donkey Kong

Printed on June 3, 2025

Was working great until today. Major de-sync on the screen. Looks very much like horizontal overflow/no sync.

Pin 6 on p7 is sync signal, easy to verify but not present. Looks like failure on the sender board. Other colors look fine.

Vsync tested fine (on the tube side) Hsync *looks* fine on the tube side but its harder to test for, see service POTs for Vsync test.



Date: 2025-05-23, **Status:** Not-Playable



Ordered a <https://www.arcadepartsandrepair.com/store/rebuild-kits/game-pcb-cap-kits/nintendo-donkey-kong-game-pcb-cap-kit-nichicon/>
Recap kit for the TKG-4 version.

Date: 2025-05-28, **Status:** Not-Playable