



# Stacker

*Printed on May 26, 2025*

---

Throws err 5 or 3, well documented as IR sensor failure. Box has little IR sensors to see if a prize is dispensed or not, apparently they fail often.  
Could get new ones from LAI but wont know price without calling/consulting.  
Game is also just buggy, settings menu feels like it resets at random. Maybe a low nvram battery?  
Also the attract mode is always on, even at the lowest setting. Extremely annoying repetitive voice too.  
Vol knob/speaker setup is crunchy and loud. Minimum volume level is still too loud

---

**Date:** 2025-05-26, **Status:** Buggy